

1911Z 12 APR 64

TO : DIRECTOR

25X1A

FROM: [REDACTED]

ACTION: *OPS 1-8*

PRIORITY

INFO:

TOR: 1118Z 12 APR 64

IN 72919

25X1A

TO

[REDACTED]

2527

25X1A

S-184A 120200Z

25X1A

[REDACTED]

1. 723,37

2. 100

3. NORMAL

25X1A

[REDACTED]

1. 701,705,20,9,52,13,1016,1002

25X1A

2. 00

25X1A 3. SOME LOW LEVEL 400 CYCLE FROM [REDACTED]

[REDACTED]

1. 2

25X1A 2. NO ACTIVITY

[REDACTED]

1. 1,4,2,4

2. NO ACTIVITY

RADIO AND NAVAIDS

SATISFACTORY

SECRET

25X1A [REDACTED] 7 (IN 72919)

SECRET

PAGE TWO

25X1A [REDACTED] NBR 3

RPM SENSOR FAILED DURING MISSION INDICATING RPM BELOW 75 PERCENT
ON ALL CHIRPS THEREAFTER. AC SENSOR FAILED TO OPERATE ON
DESCENT. ALL CHIRPS NORMAL LENGTH WITH NO DROPOUTS.

END OF MESSAGE

SECRET